

Generate Collection

Search Results - Record(s) 16 through 16 of 16 returned.

☐ 16. Document ID: US 4748511 A		
L1: Entry 16 of 16	File: USPT	May 31, 1988
DOCUMENT-IDENTIFIER: US 4748511 A TITLE: Teleradiology system	358/43	3
The modem dials the number and tries to establish a link. If the line is busy or a similar problem occurs, the modem will immediately re-dial the number three times before giving up. If a link still cannot be established, the modem posts a message to the CPU, which prints an "idle" message on line 5 of the call menu (if it is displayed) and all of the tagged images are marked with a "not sent". The user must initiate the call again before transmission can be achieved. Full Title Citation Front Review Classification Date Reference Claims KWWC Draws Desc Image		
Generate Collection		
Terms		Documents
immediately redial\$ or immediately re-dial\$		16
Display 15 Documents, starting with Document: 16		

Display Format: KWIC Change Format